

**Bedienungsanleitung****Kohlefilter****Instruction Manual****Charcoal filter**

**Abbildung zeigt das Modell CF110**  
**Illustration shows model CF110**

## Inhalt / Index

|                                     |   |
|-------------------------------------|---|
| 1. Einbau Kohlefilter .....         | 2 |
| 2. Geräteliste.....                 | 4 |
| 1. Installation carbon filter ..... | 7 |
| 2. List of devices.....             | 9 |

Sehr geehrter Kunde! Sehr geehrte Kundin! Wir möchten Ihnen herzlich danken, dass Sie sich zum Erwerb eines Produkts aus unserem reichhaltigen Angebot entschieden haben. Lesen Sie die gesamte Bedienungsanleitung, bevor Sie das Gerät zum ersten Mal benutzen.

### 1. Einbau Kohlefilter

**Kohlefilter:** CF110, CF115, CF130, CF135, CF140, CF145, CF150, CF155, CF160, CF170, CF180, CF190  
C02, C04, C06


#### **HINWEIS:**

- Verwenden Sie Schutzhandschuhe!
- Vor Montage Netzstecker ziehen!
- Kohlefilter nur im Umluftbetrieb verwenden!



Der Kohlefilter enthält keine problematischen Schadstoffe und kann über die Restmülltonne entsorgt werden.

#### Schritt 1




Entfernen Sie den/die Fettfilter. **Die Kohlefilter werden auf beiden Seiten des Motorgehäuses befestigt.**

#### Schritt 2


Sollte sich die Netzanschlussdose innerhalb der Kaminverkleidung befinden, müssen Sie evtl. die

Kaminverkleidung abbauen, um an die Anschlussdose heran zu kommen.



1. Nach links drehen = Der darauf befindliche Kohlefilter wird zum Entfernen nach links gedreht
2. Nach rechts drehen = Der Kohlefilter wird auf den Motor gesetzt und leicht nach rechts gedreht oder geruckelt bis er festsitzt.

### Schritt 3



Setzen Sie den Kohlefilter mit der Haltevorrichtung (Halteklammern) seitlich an den Motor und drehen Sie, bis der Filter einrastet.

### Schritt 4

Befestigen Sie die Metall/Alu-Filter wieder.

**Tipp:** Wechseln Sie die Kohlefilter (je nach Benutzung der Haube) alle drei bis sechs Monate. Reinigen Sie die Fettfilter regelmäßig für einen einwandfreien Betrieb des Motors)



Bestellen Sie die Kohlefilter unter  
**[www.pkm-online.de](http://www.pkm-online.de)**

**⚠️ WARNUNG!** Befestigen Sie den Kohlefilter sicher und ordnungsgemäß. Ansonsten kann sich der Kohlefilter lockern und somit Gefahren verursachen.

**HINWEIS!** Die Abzugsleistung verringert sich bei eingebauten Kohlefiltern. Kohlefilter sind nicht Teil des Lieferumfangs.

## 2 Geräteliste

| Artikelbezeichnung | Artikel.Nr. | Kohlefilter/Artikel Nr. |
|--------------------|-------------|-------------------------|
| BS36-60AIXPH       | 50794       | 2 x CF150 (50440)       |
| BS38-60ABPH        | 50796       | 1 x CF150 (50440)       |
| BS38-60AWPH        | 50795       | 1 x CF150 (50440)       |
| BS47-60ABTH        | 50797       | 2 x CF150 (50440)       |
| S13-60BWPY         | 50821       | 2 x CF140 (50510)       |
| S23-60ABPX2        | 50849       | 1 x CO4 (50223)         |
| DSH60-BL           | 50662       | 1 x CO4 (50223)         |
| KH-60KH-S          | 50586       | 2 x CF130 (50053)       |
| KH9039H            | 50829       | 2 x CF130 (50053)       |
| KH-GSH-60B         | 50596       | 2 x CF140 (50510)       |
| KHS20-60H          | 50830       | 2x CF150 (50440)        |
| KHS34-80           | 50862       | 1 x CO4 (50223)         |
| KHU-60EB           | 50548       | 2 x CF130 (50053)       |
| KHU-60EB2X         | 50759       | 1 x CO4 (50223)         |
| KHU-601            | 50540       | 1 x CO4 (50223)         |
| KHU-602            | 50541       | 1 x CO6 (50405)         |
| KHU-602-H          | 50585       | 2 x CF152 (50032)       |
| KHU-603            | 50547       | 2 x CF110 (50007)       |
| KHUBH3001X         | 50863       | 1x CO4 (50223)          |
| UBH5000SX          | 50831       | 1 x CO6 (50405)         |
| S22-60BBPYL        | 50836       | 2 x CF140 (50510)       |
| S22-60BWPYL        | 50837       | 2 x CF140 (50510)       |
| S23-60AWPX         | 50832       | 1 x CO4 (50223)         |
| S47-60ABTH         | 50858       | 2 x CF150 (50440)       |
| S47-60AWTH         | 50858       | 2 x CF150 (50440)       |
| 6004BH             | 50839       | 2 x CF150 (50440)       |
| 6004W              | 50430       | 2 x CF150 (50440)       |
| 6090-2H            | 50458       | 2 x CF130 (50053)       |
| 6091BH             | 50838       | 2 x CF130 (50053)       |
| 6091H              | 50163       | 2 x CF130 (50053)       |
| 8060GZ             | 50346       | 2 x CF110(50007)        |
| 8090GZ             | 50347       | 2 x CF110 (50007)       |
| 8099GISZ           | 50355       | 2 x CF110 (50007)       |
| 8099 ISZ           | 50331       | 2 x CF110 (50007)       |
| 9004W              | 50448       | 2 x CF150 (50440)       |
| 9031X              | 50369       | 1 x CO4 (50223)         |
| 9031XS             | 50368       | 1 x CO4 (50223)         |
| 9039X              | 50371       | 1 x CO4 (50223)         |
| 9039XW             | 50370       | 1 x CO4 (50223)         |
| 9039Y1             | 50778       | 2 x CF155 (50753)       |

|              |       |                    |
|--------------|-------|--------------------|
| 9040-60BZ    | 50340 | 2 x CF110 (50007)  |
| 9040-90BZ    | 50341 | 2 x CF110 (50007)  |
| 9041-60HBG   | 50784 | 2 x CF130 (50053)  |
| 9041-80HBG   | 50785 | 2 x CF130 (50053)  |
| 9080BZ N     | 50455 | 2 x CF110 (50007)  |
| 9080WZ N     | 50456 | 2 x CF110 (50007)  |
| 9090-2H N    | 50466 | 2 x CF130 (50053)  |
| FS1-60BSPY   | 50659 | 2 x CF140 (50510)  |
| FS2-60BBGTY  | 50744 | 2 x CF140 (50510)  |
| GS1-60CIXPH  | 50467 | 2 x CF130 (50053)  |
| P1-60BBTX    | 50711 | 1x CF125 (50761)   |
| S2-90ABTZ    | 50534 | 2 x CF 110 (50007) |
| S3-60_ABTZ   | 50452 | 2 x CF110 (50007)  |
| S3-90ABTZ    | 50453 | 2 x CF110 (50007)  |
| S7-60ABTH    | 50489 | 2 x CF110 (50007)  |
| S7-90ABTH    | 50491 | 2 x CF110 (50007)  |
| S8-60A++IXTW | 50656 | 2 x CF180 (50867)  |
| S8-90A++IXTW | 50657 | 2 x CF180 (50867)  |
| S9-60 ABTZ   | 50624 | 2x CF110 (50007)   |
| S9-80 ABTZ   | 50623 | 2x CF 110 (50007)  |
| S13-60BBPH   | 50842 | 2x CF150 (50440)   |
| S13-60BBPY   | 50509 | 2 x CF140 (50510)  |
| S20-60 ABTY  | 50636 | 2 x CF 145 (50652) |
| S20-60 AWTY  | 50638 | 2 x CF145 (50652)  |
| S20-60ABTH   | 50855 | 2 x CF150 (50440)  |
| S20-60AWTH   | 50856 | 3 x CF150 (50440)  |
| S20-90 ABTY  | 50637 | 2 x CF145 (50652)  |
| S20-90 AWTY  | 50639 | 2 x CF145 (50652)  |
| S20-90ABTH   | 50857 | 2 x CF150 (50440)  |
| S21-60ABTH   | 50858 | 2 x CF150 (50440)  |
| S21-60 ABTY  | 50671 | 2 x CF145 (50652)  |
| S21-60AWTH   | 50859 | 2 x CF150 (50440)  |
| S21-60 AWTY  | 50672 | 2 x CF145 (50652)  |
| S21-90ABTH   | 50860 | 2 x CF150 (50440)  |
| S21-90 ABTY  | 50673 | 2 x CF145 (50652)  |
| S21-90 AWTY  | 50674 | 2 x CF145 (50652)  |
| S22-60 BBPY  | 50582 | 2 x CF140 (50510)  |
| S23-60 ABPX  | 50622 | 1 x C04 (50223)    |
| S23-60 ABPY  | 50745 | 2 x CF155 (50753)  |
| S25-60ABTH   | 50632 | 2 x CF110 (50007)  |
| S25-60AWTH   | 50633 | 2 x CF110 (50007)  |
| S26-50BBTY   | 50640 | 2 x CF140 (50510)  |
| S26-60BBTY   | 50643 | 2 x CF140 (50510)  |
| S26-60BWTY   | 50642 | 2 x CF140 (50510)  |
| S26-90BBTY   | 50643 | 2 x CF140 (50510)  |

|                |       |                    |
|----------------|-------|--------------------|
| S28-60 BBPY    | 50676 | 2 x CF140 (50510)  |
| S28-60 BWPY    | 50677 | 2 x CF140 (50510)  |
| S33-60A+BTH    | 50692 | 2 x CF115 (50696)  |
| S33-90A+BTH    | 50695 | 2 x CF115 (50696)  |
| S34-60 ABT2X   | 50748 | 1 x CO4 (50223)    |
| S34-80ABT2X    | 50749 | 1 x CO4 (50223)    |
| S50-60ABP      | 50850 | 2 x CF170 (50866)  |
| S50-90ABP      | 50851 | 2 x CF170 (50866)  |
| T1-60A++IXEZ   | 50454 | 2 x CF110 (50007)  |
| T1-90A++IXEZ   | 50463 | 2 x CF110 (50007)  |
| UBH3001X       | 50336 | 1 x CO4 (50223)    |
| UBH4060-2H     | 50468 | 2 x CF110 (50007)  |
| UBH5000H2      | 50608 | 1 x CF152 (50032)  |
| W EB1-52AIXPY  | 50713 | 2 x CF 145 (50652) |
| W S4-60A++BTZ  | 50727 | 2 x CF110 (50007)  |
| W S4-90A++BTZ  | 50722 | 2 x CF110 (50007)  |
| W S4-90A++WTZ  | 50717 | 2 x CF110 (50007)  |
| W S5-60 ABTZ   | 50728 | 2 x CF110 (50007)  |
| W S5-60 AWTZ   | 50729 | 2 x CF110 (50007)  |
| W S5-80 ABTZ   | 50731 | 2 x CF110 (50007)  |
| W T2-90A++IXTZ | 50736 | 2 x CF110 (50007)  |

Dear Customer, Thank you for purchasing one of our many quality products. Please read this entire manual before using your device for the first time.

## 1. Installation carbon filter


Carbon filter: **CF110, CF115, CF130, CF135, CF140, CF145, CF150, CF155, CF160, CF170, CF180, C02, C04, C06**

- **NOTE**  
Use protective gloves!
- Disconnect the mains plug before installation!
- Only use the charcoal filter in recirculation mode!



The carbon filter does not contain any problematic pollutants and can be disposed of in the residual waste garbage can.


### Step 1



Remove the grease filter(s). The carbon filters are attached to both sides of the motor housing.


### Step 2

If the mains connection socket is located inside the fireplace cladding, you may have to remove the fireplace cladding to access the connection socket.



2. Turn to the left = The carbon filter on it is turned to the left for removal
3. Turn to the right = The carbon filter is placed on the motor and turned or jerked slightly to the right until it is firmly in place.

### Step 3



Place the carbon filter with the retaining device (retaining clips) on the side of the motor and turn until the filter clicks into place.

### Step 4

Reattach the metal/aluminum filters.

**Tip:** Change the charcoal filters (depending on how the hood is used) every three to six months. Clean the grease filters regularly to ensure proper operation of the motor)



Order the carbon filters at  
**[www.pkm-online.de](http://www.pkm-online.de)**



**WARNING!** Attach the charcoal filter securely and properly. Otherwise, the charcoal filter may become loose and cause danger.

**NOTE!** The extraction capacity is reduced if carbon filters are installed. Carbon filters are not included in the scope of delivery.

## 2. List of devices

| item description | Artikel.Nr. | Charcoal Filter<br>/Artikel Nr. |
|------------------|-------------|---------------------------------|
| BS36-60AIXPH     | 50794       | 2 x CF150 (50440)               |
| BS38-60ABPH      | 50796       | 1 x CF150 (50440)               |
| BS38-60AWPH      | 50795       | 1 x CF150 (50440)               |
| BS47-60ABTH      | 50797       | 2 x CF150 (50440)               |
| S13-60BWPY       | 50821       | 2 x CF140 (50510)               |
| S23-60ABPX2      | 50849       | 1 x CO4 (50223)                 |
| DSH60-BL         | 50662       | 1 x CO4 (50223)                 |
| KH-60KH-S        | 50586       | 2 x CF130 (50053)               |
| KH9039H          | 50829       | 2 x CF130 (50053)               |
| KH-GSH-60B       | 50596       | 2 x CF140 (50510)               |
| KHS20-60H        | 50830       | 2x CF150 (50440)                |
| KHS34-80         | 50862       | 1 x CO4 (50223)                 |
| KHU-60EB         | 50548       | 2 x CF130 (50053)               |
| KHU-60EB2X       | 50759       | 1 x CO4 (50223)                 |
| KHU-601          | 50540       | 1 x CO4 (50223)                 |
| KHU-602          | 50541       | 1 x CO6 (50405)                 |
| KHU-602-H        | 50585       | 2 x CF152 (50032)               |
| KHU-603          | 50547       | 2 x CF110 (50007)               |
| KHUBH3001X       | 50863       | 1x CO4 (50223)                  |
| UBH5000SX        | 50831       | 1 x CO6 (50405)                 |
| S22-60BBPYL      | 50836       | 2 x CF140 (50510)               |
| S22-60BWPYL      | 50837       | 2 x CF140 (50510)               |
| S23-60AWPX       | 50832       | 1 x CO4 (50223)                 |
| S47-60ABTH       | 50858       | 2 x CF150 (50440)               |
| S47-60AWTH       | 50858       | 2 x CF150 (50440)               |
| 6004BH           | 50839       | 2 x CF150 (50440)               |
| 6004W            | 50430       | 2 x CF150 (50440)               |
| 6090-2H          | 50458       | 2 x CF130 (50053)               |
| 6091BH           | 50838       | 2 x CF130 (50053)               |
| 6091H            | 50163       | 2 x CF130 (50053)               |
| 8060GZ           | 50346       | 2 x CF110(50007)                |
| 8090GZ           | 50347       | 2 x CF110 (50007)               |
| 8099GISZ         | 50355       | 2 x CF110 (50007)               |
| 8099 ISZ         | 50331       | 2 x CF110 (50007)               |
| 9004W            | 50448       | 2 x CF150 (50440)               |
| 9031X            | 50369       | 1 x CO4 (50223)                 |
| 9031XS           | 50368       | 1 x CO4 (50223)                 |
| 9039X            | 50371       | 1 x CO4 (50223)                 |
| 9039XW           | 50370       | 1 x CO4 (50223)                 |

|              |       |                    |
|--------------|-------|--------------------|
| 9039Y1       | 50778 | 2 x CF155 (50753)  |
| 9040-60BZ    | 50340 | 2 x CF110 (50007)  |
| 9040-90BZ    | 50341 | 2 x CF110 (50007)  |
| 9041-60HBG   | 50784 | 2 x CF130 (50053)  |
| 9041-80HBG   | 50785 | 2 x CF130 (50053)  |
| 9080BZ N     | 50455 | 2 x CF110 (50007)  |
| 9080WZ N     | 50456 | 2 x CF110 (50007)  |
| 9090-2H N    | 50466 | 2 x CF130 (50053)  |
| FS1-60BSPY   | 50659 | 2 x CF140 (50510)  |
| FS2-60BBGTY  | 50744 | 2 x CF140 (50510)  |
| GS1-60CIXPH  | 50467 | 2 x CF130 (50053)  |
| P1-60BBTX    | 50711 | 1x CF125 (50761)   |
| S2-90ABTZ    | 50534 | 2 x CF 110 (50007) |
| S3-60_ABTZ   | 50452 | 2 x CF110 (50007)  |
| S3-90ABTZ    | 50453 | 2 x CF110 (50007)  |
| S7-60ABTH    | 50489 | 2 x CF110 (50007)  |
| S7-90ABTH    | 50491 | 2 x CF110 (50007)  |
| S8-60A++IXTW | 50656 | 2 x CF180 (50867)  |
| S8-90A++IXTW | 50657 | 2 x CF180 (50867)  |
| S9-60 ABTZ   | 50624 | 2x CF110 (50007)   |
| S9-80 ABTZ   | 50623 | 2x CF 110 (50007)  |
| S13-60BBPH   | 50842 | 2x CF150 (50440)   |
| S13-60BBPY   | 50509 | 2 x CF140 (50510)  |
| S20-60 ABTY  | 50636 | 2 x CF 145 (50652) |
| S20-60 AWTY  | 50638 | 2 x CF145 (50652)  |
| S20-60ABTH   | 50855 | 2 x CF150 (50440)  |
| S20-60AWTH   | 50856 | 3 x CF150 (50440)  |
| S20-90 ABTY  | 50637 | 2 x CF145 (50652)  |
| S20-90 AWTY  | 50639 | 2 x CF145 (50652)  |
| S20-90ABTH   | 50857 | 2 x CF150 (50440)  |
| S21-60ABTH   | 50858 | 2 x CF150 (50440)  |
| S21-60 ABTY  | 50671 | 2 x CF145 (50652)  |
| S21-60AWTH   | 50859 | 2 x CF150 (50440)  |
| S21-60 AWTY  | 50672 | 2 x CF145 (50652)  |
| S21-90ABTH   | 50860 | 2 x CF150 (50440)  |
| S21-90 ABTY  | 50673 | 2 x CF145 (50652)  |
| S21-90 AWTY  | 50674 | 2 x CF145 (50652)  |
| S22-60 BBPY  | 50582 | 2 x CF140 (50510)  |
| S23-60 ABPX  | 50622 | 1 x C04 (50223)    |
| S23-60 ABPY  | 50745 | 2 x CF155 (50753)  |
| S25-60ABTH   | 50632 | 2 x CF110 (50007)  |
| S25-60AWTH   | 50633 | 2 x CF110 (50007)  |
| S26-50BBTY   | 50640 | 2 x CF140 (50510)  |
| S26-60BBTY   | 50643 | 2 x CF140 (50510)  |
| S26-60BWTY   | 50642 | 2 x CF140 (50510)  |

|                |       |                    |
|----------------|-------|--------------------|
| S26-90BBTY     | 50643 | 2 x CF140 (50510)  |
| S28-60 BBPY    | 50676 | 2 x CF140 (50510)  |
| S28-60 BWPY    | 50677 | 2 x CF140 (50510)  |
| S33-60A+BTH    | 50692 | 2 x CF115 (50696)  |
| S33-90A+BTH    | 50695 | 2 x CF115 (50696)  |
| S34-60 ABT2X   | 50748 | 1 x CO4 (50223)    |
| S34-80ABT2X    | 50749 | 1 x CO4 (50223)    |
| S50-60ABP      | 50850 | 2 x CF170 (50866)  |
| S50-90ABP      | 50851 | 2 x CF170 (50866)  |
| T1-60A++IXEZ   | 50454 | 2 x CF110 (50007)  |
| T1-90A++IXEZ   | 50463 | 2 x CF110 (50007)  |
| UBH3001X       | 50336 | 1 x CO4 (50223)    |
| UBH4060-2H     | 50468 | 2 x CF110 (50007)  |
| UBH5000H2      | 50608 | 1 x CF152 (50032)  |
| W EB1-52AIXPY  | 50713 | 2 x CF 145 (50652) |
| W S4-60A++BTZ  | 50727 | 2 x CF110 (50007)  |
| W S4-90A++BTZ  | 50722 | 2 x CF110 (50007)  |
| W S4-90A++WTZ  | 50717 | 2 x CF110 (50007)  |
| W S5-60 ABTZ   | 50728 | 2 x CF110 (50007)  |
| W S5-60 AWTZ   | 50729 | 2 x CF110 (50007)  |
| W S5-80 ABTZ   | 50731 | 2 x CF110 (50007)  |
| W T2-90A++IXTZ | 50736 | 2 x CF110 (50007)  |

|                        |                        |
|------------------------|------------------------|
| Änderungen vorbehalten | Subject to alterations |
| <b>Stand</b>           | <b>Updated</b>         |
| 23.09.2024             | 09/23/2024             |

© PKM GmbH & Co. KG, Neuer Wall 2, 47441 Moers