




Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb
 / Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļi



Pos.	Part No.
1	A 963 131 NU
2	A 963 132 NU
3	A 963 146 NU




DIN EN 1717
 HD

A 3318 AA
 F 1091 AA


9a




9a



IEC 60364






9b



Ø20
 SELV 6,5V



B1

B2



IEC 60364

9c



Ideal Standard International NV
 Corporate Village - Gent Building
 Da Vincilaan 2
 1935 Zaventem
 Belgium

www.idealstandardinternational.com




EASY BOX
 A 1000 NU






Ideal Standard

0621 / A 866 090 40
 Made in Germany



9a





		P Prüfdruck bar		MAX. 10		5	
				0,5		1	
		T °C		MAX. 80		65	
				55		55	